

FROM: Emile Berries
SENT: 14 June 2017 16H00
TO: All Franchisees

SUBJECT: H2O Bottling Plants CIP - (Cleaning in Place) Procedures / Directive

Dear H2O International Franchisees,

It has been brought to our attention by Gordon Reid that the Cleaning in Place Procedures (CIP), recommended by Gordon are not being implemented by H2O International Franchisees who currently bottle water.

Ongoing reports performed by Gordon show that the water quality tested from H2O Bottling Plants are deteriorating instead of improving.

This is a concern for Gordon as he feels the recommendations made are not been properly followed. He stresses that it is vitally important for all H2O Bottling Plants to regularly perform the CIP Procedures.

See the link below that explains, step by step, how this is to be done.

http://h2o-online.co.za/sdm_downloads/h2o-international-il9-filtration-sterilization-installation-manual1-pdf/

(If the link doesn't work this document can be found here: H2O-Online Master Documents Library > Tech Support > Installation Drawings and Instructions: Standard H2O Bottling plant Installation and CIP Manual)

In order for us not to compromise on quality, Gordon recommends that all H2O International Bottling Plants put these CIP steps & procedures in place and they are performed every 2 weeks.

Please contact me if you need any assistance. It is vital that all H2O International Franchisees are delivering water of a very high quality. The only way we, as a group, can maintain this high quality is by ensuring that the Bottling Plants are regularly sterilized / sanitised every two weeks.

Kind regards,
Emile Berries

Technical Manager
H2O International SA
0795096619